



Co-funded by
the European Union



Speed limit and prohibited area within the port limits

DESCRIPTION	Sandybay VTS contacts MV Seabass to provide information on the speed limit in the port area, and a prohibited area within the port limit.	
PARTICIPANTS	VTS operator, Officer of the Watch	
PROMPTS	VTS	Establish contact with MV Seabass.
	Ship	Reply to Sandybay VTS and establish contact.
	VTS	Provide MV Seabass with the following information (use a message marker): <ul style="list-style-type: none">- Maximum speed limit within the port (6 knots). Repeat the information.- Inside the port limit there is a prohibited area, marked with yellow buoys on the chart. The area is situated between buoys Charlie 4 and Charlie 3. Repeat the information.
	Ship	Appropriately confirm the received information by reading it back.
	VTS	Inform the vessel to stand by on VHF channels 08 and 16.
	Ship	Appropriately confirm the provided information by reading it back. End the exchange.



UNIVERZA
V LJUBLJANI



REPUBLIC OF SLOVENIA
MINISTRY OF INFRASTRUCTURE
SLOVENIAN MARITIME ADMINISTRATION